


| | | | |
|-------|--|----------|-------------------------|
| BIKE | HONDA VFR800F | PART NO. | RHA - 168 |
| YEAR | 2014-Current | FIT KITS | Z039.10543 |
| NOTES | Where not supplied use original fittings | FEATURES | DB KILLER Z038.10043(V) |



- | | |
|--|--|
| 1 Serket Silencer 400mm RSC330 | 8 M8x25mm Washer (Z017.10825) |
| 2 Connecting Pipe CP844 | 9 Bump Stop (Z028.10021) |
| 3 47-51mm Clamp (Z016.10003) | 10 2 x Nylon Washer (Z017.12748) |
| 4 2 x Rubber Coated Springs (Z028.10030) | 11 M6x12mm Washer (Z017.10617) |
| 5 M8x50mm Cap Head Bolt (Z017.10078) | 12 M6x20mm Button Head Bolt (Z017.12747) |
| 6 Alloy Bolt Finisher (Z026.20068) | 13 M6 Nyloc Nut (Z017.10033) |
| 7 M8 Nyloc Nut (Z017.10062) | |

| | |
|------------|--------------|
| E-MARK | RHA168 3070 |
| ISSUE NO. | 01 |
| DATE | 20/01/16 |
| AUTHORISED | M.Ydlibi |
| CHECKED | |

NOTE: ENSURE SCORPION SYSTEM IS CLEAR OF MOVING PARTS AND ALL ORIGINAL FUNCTIONS WORK CORRECTLY.



A) Remove original exhaust from bike, taking care to keep all original components in a safe place.

B) Refit Scorpion exhaust as per line diagram above.

C) When fitted take bike for a short ride to ensure all functions are correct.

D) When bike & exhaust are cool enough check all nuts and bolts are still secure.

Cleaning instructions overleaf:

Box: PLOCK 2

| | | | |
|-------|---------------|----------|-------------------------|
| BIKE | HONDA VFR800F | PART NO. | RHA - 168 |
| YEAR | 2014-Current | FIT KITS | Z039.10543 |
| NOTES | | FEATURES | DB KILLER Z038.10043(V) |

Thank you for purchasing your Scorpion Silencer.

Care of your exhaust: Please refrain from cleaning silencer with heavy solvents or abrasives!

Vielen Dank Fur den kauf eines Scorpion Schalldampfers! Pflegehinweis: Bitte verwenden Sie niemals Scheuermittel oder aggressive Reiniger zur Pflege Ihres Auspuffes!

Merci d'avoir choisi un echappement Scorpion.

Entretien de votre silencieux: Ne pas utiliser de solvants ou de produits abrasifs!

"Muchas gracias por adquirir un Silencioso Scorpion. Le recomendamos no limpiar el silencioso con productos abrasivos o aquellos que contengan disolventes."